FEB 2 0 2008

03226.000110 PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

in to t atom of.	Examiner: K. Feggins
JOHN HILBERT)
Appl. No.: 10/673,044	Group Art Unit: 2861
Filed: September 26, 2003)
For: DIRECT THERMAL PRINTER	·)
U.S. Patent No.: 7,256,803 B2	·)
Issued: August 14, 2007) February 19, 2008
Commissioner for Patents P.O. Roy 1450	Certificate

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 323

FEB 2 2 2008

of Correction

Sir:

In re Patent of

Alexandria, VA 22313-1450

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

02/21/2008 HBELETE1 00000003 7256803

81 FC:1811

RECEIVED WERPO

FEB 2 2 2008

Patentee's undersigned attorney may be reached in our Costa Mesa,

California office by telephone at (714) 540-8700.

112

All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Frank L. Cire

Attorney for Patentee Registration No.: 42,419

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

FCHS_WS 1650262v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

: 7,256,803 B2 PATENT NO.

DATED : August 14, 2007

INVENTOR(S) : Hilbert Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 16, "having" should read -- has --;

Line 29, "0.3 mill-" should read -- 0.3 milli- --;

Line 39, "must." should read -- must --;

Line 46, "use" should read -- using --; and

Line 47, "sinks" should read -- sinks. --.

COLUMN 2:

Line 10, "lasers" should read -- laser --; and

Line 59, "discreet" should read -- discrete --.

COLUMN 3:

Line 10, "to head" should read -- to heat --.

COLUMN 5:

Line 6, "discreet" should read -- discrete --.

COLUMN 6:

Line 3, "be" should read -- by --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) 1650251v1(Form#30)

PATENT NO. <u>7,256,803 B2</u> RECEIVED-USP TO

No. of add'l coples ... @ 30¢ per page

FEB 2 2 2008



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,256,803 B2

DATED

: August 14, 2007

INVENTOR(S) : Hilbert

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 16, "having" should read -- has --;

Line 29, "0.3 mill-" should read -- 0.3 milli- --;

Line 39, "must." should read -- must --;

Line 46, "use" should read -- using --; and

Line 47, "sinks" should read -- sinks. --.

COLUMN 2:

Line 10, "lasers" should read -- laser --; and

Line 59, "discreet" should read -- discrete --.

COLUMN 3:

Line 10, "to head" should read -- to heat --.

COLUMN 5:

Line 6, "discreet" should read -- discrete --.

COLUMN 6:

Line 3, "be" should read -- by --.

received-uspto חטבונים ליונים ליונים

FEB 2 2 2008

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. 7,256,803 B2

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) 1650251v1(Form#30)